


Tip C



D	H	M
20	10	M 6
20	15	M 6
20	20	M 6
25	10	M 6
25	15	M 6
25	20	M 6
25	25	M 6
30	10	M 8
30	15	M 8
30	20	M 8
30	25	M 8
30	30	M 8
40	10	M 8
40	20	M 8
40	25	M 8
40	30	M 8
40	40	M 8
50	20	M 10
50	25	M 10
50	30	M 10
50	35	M 10
50	40	M 10
50	50	M 10
60	20	M 10
60	25	M 10
60	30	M 10
60	35	M 10
60	40	M 10
60	50	M 10
60	60	M 10
70	30	M 12
70	40	M 12
70	50	M 12
70	60	M 12
75	25	M 12
75	30	M 12
75	40	M 12
75	50	M 12
75	60	M 12
80	30	M 12
80	40	M 12
80	50	M 12
80	60	M 12
100	30	M 16
100	40	M 16
100	50	M 16
100	60	M 16
100	70	M 16
100	80	M 16